

# **SAMPLE ENVIRONMENT JRA MEETING**

## **NMI3 MEETING, PSI**

**30th MARCH 2009**

### **DRAFT AGENDA**

- 1. Welcome & Introduction**                      Zoë Bowden, ISIS
  
- 2. Brief Introductions to the Tasks:**
  - a. High Pressure Task                      Oleg Kirichek, ISIS
  - b. Levitation Furnace Task                Eddy Lelièvre-Berna, ILL
  - c. Gas Adsorption Task                    Dirk Wallacher, HMI
  
- 3. Discussion of Tasks**                      Task leaders
  - a. Technical challenges
  - b. Ideas exchange
  
- 4. Planning and delivery**  
(who is doing what, when)
  
- 5. Next meeting – where, when?**
  
- 6. Next meeting – what will we be reporting?**
  
- 7. Ray tracing applications**                Eddy